HARVARD HISTORICAL COMMISSION

13 AYER ROAD •

HARVARD, MASSACHUSETTS 01451



APPLICATION FOR CERTIFICATE

Please read the instructions before you complete this form.

CERTIFICATE OF:	X APPROPRIATENESS	□ NON-APPLICABILITY	☐ HARDSHIP	
CONTACT INFORMATI	ON:			
Property Address	5 ELM ST	HARVARD	MA	
Property Owner Name	Scott HA	YWARD	1.343	
Applicant Name	SAME	1		
Applicant Address	SAME AC	DRANKAT	D	
Telephone	978,008	SISIPLIER		
E-Mail Address	SCOTTO LIAI	WARDGENER	MODRE	MAN
		CALLED CLOCK	401010 -C	VIV)
DESCRIPTION OF WORK	C PROPOSED: /Vou may attac	ch additional pages to describe you		
If project consists of seve	ral different tasks, begin by list	ing each task, then describe each to	r proposea work) ask in detail including drawi	ings and
photos as necessary. You	may attach additional pages to	o describe your proposed work.	isk in detail melading drawi	rigs and
0	_			
	$\gamma_{i,i}$			
1	ittachul	(
1000	00000			. 2-
			Grades Gistan	100
				20
			DEC	高温
			N	
			***************************************	90
			工	27
			Ö	50
			2	CLERK
			ω	245
IST OF ATTACHMENTS	: (Please check off the listed it	tems when attached)		
Site Plan (showing change		Construction Drawings		
Photos taken from street Photos of areas to be wo		Building material samples		
APPLICANT SIGNATURE	E (Sign to submit application)		D	ATE
11 - 1.1	moul	(2)	lo.	
	1		1/2	.24.
GRAMT OF EXTENSION	. (With the following signature	re, the applicant grants permission	n to the Commission to re	view the
opuration at its next sche	duled monthly meeting in lieu o	of holding a Special meeting.)		
Very Nas	me 1		15	· > U. 1
179	10.00			27.
(/				
V				

Description of Work Proposed

5 Elm Street
Deborah Sauve and Scott Hayward
978-808-3651 - c
scott@harvardgeneralstore.com

The property at 5 Elm Street is composed of two structures, a four bedroom home to the south and a barn to the north. Both structures are of post and beam construction. The two-over-two-room front of the home dates to the mid 18th century and faces east. An 1840's post and beam addition extends to the west. More additions, some as recent as the 1990's, have been added to this wing. The work proposed is on the home; there will be no work performed on the barn.


We are renovating the home at this time for two reasons. Some portions of the home suffered extensive ice damage during recent storms, in 2010 and 2015. This damage is located almost entirely on the most recent additions at the rear of the house. However, some maintenance work will have to be performed to fix rotting gutters on the older portion of the home. At the same time we plan to complete a much needed renovation of the kitchen and upstairs baths that have not been updated for at least 30 or 40 years.

The most recent additions can be characterized as shed-roofed areas accommodating modern functions that required additional space, for instance, when bathrooms, a breakfast room, a basement laundry, deck and sunroom were added. The construction of these areas was shoddy and little thought was given to a comprehensive design or their compatibility with the existing structure.

The exterior construction we propose consists of removing these rotting structures and replacing them within a comprehensive building envelope and extending the existing roof to shelter it. Protecting the home from the elements is our primary concern. As a consequence of tearing off the 1990's sunroom, we propose adding a three season porch to the north facade and reconfiguring the back deck into a more modest design.

I have attached photos of the home, a site plan, existing conditions drawings, and schematic drawings of the renovations. Please contact me for more information if required.

South an Elm. Looking but






Elm Street Facode



Twith on Elm Looking but Looking Cast on Loven Love






morth founds




north freade



West Facado






SITE PLAN OF LAND IN Harvard, Mas


PREPARED FOR

SCALE: 1"= 20"

David E. Ross Associat

CIVIL ENGINEERS - LAND SURV ENVIRONMENTAL CONSULTANT





SAUVE-HAYWARD HOUSE RENOVATION WHNDY J. COTE-MAGAN Harvard, MA


5 Elm Street Harvard, MA 01451

PROPOSED EXTERIOR ELEVATIONS

z ≯ ↓ w

A-2

PROGRESS DRAWING NOT FOR CONSTRUCTION




「后とならいから

M

Exterior Elevation - South

田田田



ってい 0 0

Exterior Elevation - West

EVENETION S 020