

FIELD REPORT

Nitsch Project #:	12808	Date:	December 5, 2019
Client:	Pine Hill Village, LLC	Time:	9:30 AM
Project:	Pine Hill Development	Location:	Harvard, Massachusetts
Weather:	Sunny, 38°F		
Present:	Gavin Graham, Nitsch Engineering		

The purpose of this site visit was to observe general site conditions, observe general construction activities, and erosion and sedimentation control measures. This site visit satisfies the weekly site visit required by Nitsch Engineering. The site experienced a Nor'easter over the course of Sunday 12/1- Tuesday 12/3 which left the site covered in almost two feet of snow. The following was noted:

1. Burl Land Clearing & Stump Grounding was on site removing cut trees at the time of the site visit. Clearing of the site is moving forward (Figures 1 + 2).
2. Contractor was on site repairing damaged erosion control fences (Figures 3 + 4).



Figure 1



Figure 2



Figure 3



Figure 4

CLIENT: Nitsch Project #
Date from 1st page
Page 2 of 2

Ongoing Recommendations:

- Contractor to maintain stabilized construction entrance
- Contractor to maintain erosion control barriers

If there are any questions, please call:

Gavin Graham

Gavin Graham
Project Designer

GG

cc: Project File

Q:\12808 Pine Hill 40B\Civil\CA\Site Visit\Field Reports\2019-12-05